

Date: Tuesday, 22/04/2008 10:24:47 AM
 User: Julie Lecocq

Process Sheet

Customer :	CU-DAR001 Dart Helicopters Services	Drawing Name :	206 A/B HIGH GEAR SKIDTUBE
Job Number :	38719		
Estimate Number :	10170		
P.O. Number :		Part Number :	D206642212
This Issue :	22/04/2008	Drawing Number :	N/A
Prsht Rev. :	NC	Project Number :	N/A
First Issue :	/ /	Drawing Revision :	L
Previous Run :	38718	Material :	
Written By :		Due Date :	12/05/2008
Checked & Approved By :	<u>JLO 08.4.22</u>	Qty:	1 Um: Each
Comment :	Est Rev:K 05.07.14 ECN 847 & 901; Add Tow Ring and GHW Kit KJ/CP/JLM Est Rev:L 07-12-04 ECN 1080p DD verified by:		

Additional Product

Job Number:



Seq. #:	Machine Or Operation:	Description :
---------	-----------------------	---------------

1.0	DC	DOCUMENT CONTROL
-----	----	------------------



Comment: DOCUMENT CONTROL

Photocopy bluefile & type labels per PPP206-642-212 CHG004

508/06/18 08.4.23 JLD

2.0	38719A	HIGH GEAR SKIDTUBE ASSEMBLY 206 A/B
-----	--------	-------------------------------------



Comment: Sub-Component HIGH GEAR SKIDTUBE ASSEMBLY 206 A/B
 D206-642-241 B 38719A SP

3.0	PACKAGING 1	PACKAGING RESOURCE #1
-----	-------------	-----------------------



Comment: PACKAGING RESOURCE #1
 Pick Packing Kit

4.0	D206651041	206A/B GHW
-----	------------	------------



Comment: Qty.: 1.0000 Each(s)/Unit Total: 1.0000 Each(s)

Pick: Packing Kit

Qty Part Number Description Batch

1 D206-651-041 GHW Kit 31294

1 D206-642-241(REF)

SY

5.0	D2652	Bushing
-----	-------	---------



Comment: Qty.: 16.0000 Each(s)/Unit Total: 16.0000 Each(s)

Pick: Packing Kit

Qty Part Number Description Batch

16 D2652

Bushing

388/5

8/5/26

SV

Dart Aerospace Ltd

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____
 QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

Date: Tuesday, 22/04/2008 10:24:47 AM
User: Julie Lecocq

Process Sheet

Customer: CU-DAR001 Dart Helicopters Services

Drawing Name: 206 A/B HIGH GEAR SKIDTUBE

Job Number: 38719

Part Number: D206642212

Job Number:



Seq. #: Machine Or Operation: Description :

6.0 D2655 Ring



Comment: Qty.: 1.0000 Each(s)/Unit Total : 1.0000 Each(s)

Pick: Packing Kit

Qty Part Number Description Batch

1 D2655 Tow Ring 34613

SP

7.0 D26652 Saddle, RH Fwd Aft Out 206



Comment: Qty.: 2.0000 Each(s)/Unit Total : 2.0000 Each(s)

Pick: Packing Kit

Qty Part Number Description Batch

2 D2665-2 Saddle B38750

* New Batch

AS 08/06/17 (X)

8.0 D26662 Saddle, RH Fwd Aft In 206



Comment: Qty.: 2.0000 Each(s)/Unit Total : 2.0000 Each(s)

Pick: Packing Kit

Qty Part Number Description Batch

2 D2666-2 Saddle 36627

SP

9.0 D2712 Set Screw



Comment: Qty.: 10.0000 Each(s)/Unit Total : 10.0000 Each(s)

Pick: Packing Kit

Qty Part Number Description Batch

10 D2712 Set Screw 34628

(2) 37165

SP

10.0 D2884 Saddle Spacer



Comment: Qty.: 2.0000 Each(s)/Unit Total : 2.0000 Each(s)

Pick: Packing Kit

Qty Part Number Description Batch

2 D2884 SADDLE SPACER 35497

SP

11.0 D2885 Saddle Spacer



Comment: Qty.: 2.0000 Each(s)/Unit Total : 2.0000 Each(s)

Saddle Spacer

37342

8/5/26

SP (A)

Dart Aerospace Ltd

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

Date: Tuesday, 22/04/2008 10:24:47 AM
User: Julie Lecocq

Process Sheet

Customer: CU-DAR001 Dart Helicopters Services

Drawing Name: 206 A/B HIGH GEAR SKIDTUBE

Job Number: 38719

Part Number: D206642212

Job Number:



Seq. #: Machine Or Operation: Description :

12.0 AN341A Bolt



Comment: Qty.: 8.0000 Each(s)/Unit Total : 8.0000 Each(s)

Pick: Packing Kit

Qty Part Number

Description Batch

8 AN3-41A

Bolt

107242

SD

13.0 AN45A Bolt



Comment: Qty.: 1.0000 Each(s)/Unit Total : 1.0000 Each(s)

Pick: Packing Kit

Qty Part Number

Description Batch

1 AN4-5A

Bolt

106605

SD

14.0 AN46A Bolt



Comment: Qty.: 12.0000 Each(s)/Unit Total : 12.0000 Each(s)

Pick: Packing Kit

Qty Part Number

Description Batch

12 AN4-6A

Bolt

106662

SD

15.0 AN57A Bolt



Comment: Qty.: 4.0000 Each(s)/Unit Total : 4.0000 Each(s)

Pick: Packing Kit

Qty Part Number

Description Batch

4 AN5-7A

Bolt

107013

SD

16.0 AN511A Bolt



Comment: Qty.: 4.0000 Each(s)/Unit Total : 4.0000 Each(s)

Pick: Packing Kit

Qty Part Number

Description Batch

4 AN5-11A

Bolt

105810

SD

17.0 AN644A Bolt



Comment: Qty.: 2.0000 Each(s)/Unit Total : 2.0000 Each(s)

Pick: Packing Kit

Qty Part Number

Description Batch

2 AN6-44A

Bolt

105211

8/5/26

SD

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

Date: Tuesday, 22/04/2008 10:24:47 AM
User: Julie Lecocq

Process Sheet

Customer: CU-DAR001 Dart Helicopters Services

Drawing Name: 206 A/B HIGH GEAR SKIDTUBE

Job Number: 38719

Part Number: D206642212

Job Number:



Seq. #: Machine Or Operation: Description :

18.0 AN960JD10 Washer



Comment: Qty.: 8.0000 Each(s)/Unit Total : 8.0000 Each(s)

Pick: Packing Kit

Qty Part Number

Description Batch

8 AN960JD10

Washer 9221

SP

19.0 AN960JD416 Washer



Comment: Qty.: 25.0000 Each(s)/Unit Total : 25.0000 Each(s)

Pick: Packing Kit

Qty Part Number

Description Batch

25 AN960JD416

Washer 107321

SP

20.0 AN960JD516 Washer



Comment: Qty.: 8.0000 Each(s)/Unit Total : 8.0000 Each(s)

Pick: Packing Kit

Qty Part Number

Description Batch

8 AN960JD516

Washer 107334

SP

21.0 AN960JD616 Washer



Comment: Qty.: 4.0000 Each(s)/Unit Total : 4.0000 Each(s)

Pick: Packing Kit

Qty Part Number

Description Batch

4 AN960JD616

Washer 107242

SP

22.0 MS21042L3 Nut



Comment: Qty.: 8.0000 Each(s)/Unit Total : 8.0000 Each(s)

Pick: Packing Kit

Qty Part Number

Description Batch

8 MS21042L3

Nut (or -3) 107644

8/5/20

SP

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

Date: Tuesday, 22/04/2008 10:24:47 AM
User: Julie Lecocq

Process Sheet

Customer: CU-DAR001 Dart Helicopters Services

Drawing Name: 206 A/B HIGH GEAR SKIDTUBE

Job Number: 38719

Part Number: D206642212

Job Number:



Seq. #:

Machine Or Operation:

Description :

23.0

MS21042L4

Nut



Comment: Qty.: 12.0000 Each(s)/Unit Total : 12.0000 Each(s)

Pick: Packing Kit

Qty Part Number

Description Batch

12 MS21042L4

Nut (or -4) 107478

50

24.0

MS21042L6

Nut



Comment: Qty.: 2.0000 Each(s)/Unit Total : 2.0000 Each(s)

Pick: Packing Kit

Qty Part Number

Description Batch

2 MS21042L6

Nut (or -6) 105077

8/5/06

50

25.0

QC4

INSPECT 100% KITS FOR COMPLETENESS



Comment: INSPECT 100% KITS FOR COMPLETENESS

8/8/06/18 @

26.0

PACKAGING 1

PACKAGING RESOURCE #1



Comment: PACKAGING RESOURCE #1

Identify and pack for shipping as per PPP D206-642-212

Location: D

PPP Rev: D

8/6/18

54

27.0

QC21

FINAL INSPECTION/W/O RELEASE



Comment: FINAL INSPECTION/W/O RELEASE

08/06/19

Job Completion



U 08/06/19

38719A

Dart Aerospace Ltd

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

4.2 206A/B High Gear Skidtubes

Item	Qty -211	Qty -212	Qty -213	Qty -214	Qty -241	Qty -243	Part Number	Description
	X						D206-642-211	SKIDTUBE INSTALLATION, LH
		X					D206-642-212	SKIDTUBE INSTALLATION, RH
			X				D206-642-213	SKIDTUBE INSTALLATION, LH, THRU BOLT
				X			D206-642-214	SKIDTUBE INSTALLATION, RH, THRU BOLT
	1	1	1	1	X		D206-642-241	SKIDTUBE
						X	D206-642-243	WEARSHOE KIT
	1	1	1	1			D206-651-041	* 206 GHW ADAPTER ⁽³⁾
1					1		D2650-3	SKIDTUBE ASSEMBLY
2A					18		D2651-1	* PLUG ⁽¹⁾
2B					18		D2651-3	* O-RING ⁽¹⁾
3					1		D2646	* AFT CAP ⁽¹⁾
4					2		MS27039-1-08	* SCREW ⁽¹⁾
5					2		AN960JD10L	* WASHER ⁽¹⁾
6	1		1				D2665-1	SADDLE, FWD OUT, LH
6		1		1			D2665-2	SADDLE, FWD OUT, RH
7	1		1				D2666-1	SADDLE, FWD IN, LH
7		1		1			D2666-2	SADDLE, FWD IN, RH
8	1						D2665-1	SADDLE, AFT OUT, LH
8		1					D2665-2	SADDLE, AFT OUT, RH
8			1				D2667-1	SADDLE, AFT OUT, LH
8				1			D2667-2	SADDLE, AFT OUT RH
9	1						D2666-1	SADDLE, AFT IN, LH
9		1					D2666-2	SADDLE, AFT IN, RH
9			1				D2668-1	SADDLE, AFT IN, LH
9				1			D2668-2	SADDLE, AFT IN, RH
10	8	8	8	8			AN3-41A	BOLT
11	16	16	16	16			D2652	BUSHING
12A	8	8	8	8			MS21042-3	NUT (OR MS21042L3)
12B	8	8	8	8			AN960JD10	WASHER
13	4	4	4	4			AN5-7A	BOLT
14	4	4	4	4			AN5-11A	BOLT
14A			2	2			AN5-32A	* BOLT ⁽²⁾
14B			2	2			MS21042-5	* NUT (OR MS21042L5) ⁽²⁾
15	8	8	8	8			AN960JD516	WASHER
16	12	12	12	12			AN4-6A	BOLT
17	24	24	24	24			AN960JD416	WASHER
18	12	12	12	12			MS21042-4	NUT (OR MS21042L4)
20A					4		D2648-3	WEARPAD
21A					1		D3429-1	WEARPAD
22A					1	1	D2656-13	WEARSHOE
23A					1	1	D2656-21	WEARSHOE
24A					1	1	D2656-33	WEARSHOE
26A					44		MS27039-1-08	SCREW
26B					44		AN960J10L	WASHER
26C					44		ALS7-1032-130	* INSERT ⁽¹⁾ (or AKS4-1032-130, ALS4-1032-130, AELS-1032-130)
28	2	2	2	2			AN6-44A	BOLT
29A	2	2	2	2			MS21042-6	NUT (OR MS21042L6)
29B	4	4	4	4			AN960JD616	WASHER
34	1	1	1	1			AN4-5A	BOLT
35	1	1	1	1			AN960JD416	WASHER
36	1	1	1	1			D2655	RING
37	10	10	5	5			D2712	SET SCREW
38	2	2	2	2			D2884	SADDLE SPACER
39	2	2	2	2			D2885	SADDLE SPACER

NOTES: ⁽¹⁾ DENOTES THAT PART IS INCLUDED WITH D2650-3 ASSEMBLY ABOVE⁽²⁾ MAY BE REQUIRED ON -213/-214 INSTALLATIONS⁽³⁾ NOT INSTALLED AS PART OF SKIDTUBE. USED TO MODIFY OEM GROUND HANDLING WHEELS

• COPYRIGHT © 2000 BY DART AEROSPACE USA, INC •

THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE USA, INC

Revision: L
Date: 07.10.25

w/o 38719